




TREES

**Training for Renovated Energy Efficient
Social housing**



Intelligent Energy -Europe programme, contract n° EIE/05/110/SI2.420021

Section 3: Case studies

3.6 Husby Terrasse, An example from Norway

Author :Tore Wigenstad, SINTEF

Reviewed by: Tamas Csoknyai, BUTE


Partners

Armines/Ecole Nationale Supérieure des Mines de Paris – CEP, France
Budapest University of Technology and Economics (BUTE), Hungary
EnerMa, Sweden
DHV, The Netherlands
SINTEF, Norway
University of Kassel, Center for Environmental Systems Research (UNIK),
Germany


INTRODUCTION

This paper gives additional comment to each slide to give the lecturer insight in the issues that are presented.

Case: Husby Terrasse, “ from 250 to 120 “



Husby Terrasse is situated approx. 30 km north of Trondheim, Norway.



Slide 1


Husby Terrasse consist of 110 apartments, erected in the middle of 1970. Like other domestic buildings in Norway from that decennium, energy efficiency was not given too much attention. Combined with failure in window sealing system, and poor ventilation systems, the energy consumption was measured to approx. 255 kWh/m² year

In the beginning of year 2000 the owners decided to execute a major rehabilitation. Trough this upgrading the energy target was set to 120 kWh/m² year. Approximately half of the measured energy use.




Slide 2

As the name alludes, the buildings are organized as terraces. The facades are faced to south and consist of approx. 50 % glassed area. (balcony door and rather big windows.)



Slide 3

An inspection concluded that the huge energy use where caused by poor insulation in all walls, bad U-value in windows/balcony doors, thermal bridges and poor airtightness particular in the conjunctions. The ventilation system was outdated and out of functional control as well




Slide 4

The inspection was supported by thermo photographing.

Picture taken from outside.

Average temperature [balconydoor] is 2.1 °C.
Light/Yellow colour indicate temp.up to + 7 °C.
Dark/blue colour indicate temp down to - 3 °C.



Slide 5

Thermal photo is a useful way to detect thermal bridges.

Picture is taken from inside

The picture is detecting thermal bridges in the joint between external walls and the floor (concrete slab)

The pedestals in the wall is detected as well



Slide 6

Picture is taken from inside

Thermal bridges in the joint between external walls and the ceiling/floor



Slide 7

Picture is taken from inside

Thermal bridge/air leakage in electrical switches (left)

Recommendations

- ▶ Adding insulation in walls, floor and roof
- ▶ New windows and balcony door
- ▶ Changing the ventilation from a mechanical exhaust system to a balanced system with heat recovery
- ▶ Installation of a ventilation and temperature controlling system

TREES SINTEF

Slide 8

The recommendations are reflecting what the inspection detected.

In a project like this, the package of energy related measures must be combined and adjusted to the rest of the rehabilitation activities.

An extra challenge is that the habitableness shall remain during rehabilitation period.

Taking these moments into considerations, the recommendations ended up with;

Adding insulations, new windows, new ventilation system and a new centralized temperature controlling systems for every apartment.

Insulation in walls, roofs and floors

Old construction	U-value [W/m ² K]	New construction	New U-value [W/m ² K]
Roof (balcony-floor): 120 mm concrete, 50 mm insulation, 130 mm concrete	0,48	+ 100 insulation	0,30
Floor: 130 mm concrete + 15 mm insulation	0,94	+ 100 mm insulation	0,32
Outside wall - south: 100 mm + 50 mm insulation	0,35	No action	0,35
Gabel end: Steel panels, asphalted cardboard, concrete and plaster board	1,56	+ 150 mm insulation	0,53
Outside wall north: Concrete and 100 mm wood wool slab	0,76	No action	0,76
Windows (1+1 layer)	2,5	3 layer	0,95
Balcony door (1+1 layer)	3,0	3 layer	0,95

TREES SINTEF

Slide 9

The table give U-values for old and new constructions and elements.



Slide 10

Picture is taken of outside east wall before adding insulation.

As a first step these steel panels are removed



Slide 11

Section with removed steel panels

Section covered with old windbreaker


New steel panels

Section with 1.layer of new insulation



Slide 12

Picture showing the two layers of new insulations (50 + 100 mm), and the steel frame for the panels.



Slide 13

The second layer of insulation is covered with a windbreaker.

The windbreaker is fixed by the steel framework. The frame also act as a support to the new panels



Slide 14



Outside wall finished



Slide 15

Energy efficient windows with triple glazing. 2 low emission coatings, argon gas, superspacers and wooden frame.

This construction gives a U-value of 0.95 W/m²K.



Slide 16

Balanced ventilation system with heat recovery

The heat recovery unit consist of a rotating wheel at (different speed). The heat from the extracted air is warming up a part of the wheel. When the wheel rotates, the stored heat is used to warm up the cold supply air.

About 85-90 % of the energy demand can be transferred from the extracted air.

Energy conservation	Present value ^{*)}	Pay-back	Saved energy	Saved money
Adding insulation out. wall	7 026 NOK	12,0 yrs.	2584 kWh/yr	1680 NOK/yr
Balanced ventilation	-29 426 NOK	42,5 yrs.	5247 kWh/yr	3210 NOK/yr
Controlling temperature	-3 678 NOK	22,4 yrs.	1625 kWh/yr	1057 NOK/yr
New windows	-25 729 NOK	> 50 yrs	1821 kWh/yr	1184 NOK/yr
Adding insulation floor	-18 995 NOK	> 50 yrs	1414 kWh/yr	919 NOK/yr
Adding insulation roof	-74 547 NOK	> 50 yrs	1447 kWh/yr	941 NOK/yr
Sum	-158 183 NOK	> 50 yrs	14139 kWh/yr	8991 NOK/yr

*) Negative Present value indicates that the Pay-back time is longer than the calculated Life-time for the installation

Slide 17

Different energy measures were calculated via an LCC method, and presented by “Present value”, and “Pay-back time” This in addition to the numeric value of yearly saved energy and money.

As shown in table, only “adding insulation outside wall”, achieved positive values according to “present value”. The rest of the measures achieved rather bad values.

This was communicated to the owners in advance before measures were put into action. They still wanted to implement the job.

In 2006 the first result from an ongoing logging of energy use is terminated.

Feedback from this survey shows a remarkable accordance between calculated and measured energy-values.

Acknowledgements.

Acknowledgements is due to key persons that have been involved in the project and have shared their experiences.

Special thanks to Bjørn Wackenfeldt, Tor Helge Dokka from SINTEF, Primahus AS, Arkideco and Husby boretteslag. Without input from different sectors it would not have been possible to collect useful information.